

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 24/06/2011 To: 24/06/2011

Client:	Site: BLOCK A	Location: LABORATORY		
Asset ID: MI051	Description: IEC LEAD	User: OLIVER	Test Instrument: X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.04	Ohm	Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
Polarity	24/06/2011			Pass
Overall: Pass				
Asset ID: MI052	Description: IEC LEAD	User: OLIVER	Test Instrument: X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.11	Ohm	Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
Polarity	24/06/2011			Pass
Overall: Pass				
Asset ID: MI053	Description: OVEN	User: OLIVER	Test Instrument: X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.17	Ohm	Pass
Insulation	24/06/2011	11.87	MOhm	Pass
Leakage	24/06/2011	0.23	mA	Pass
Load	24/06/2011	1.87	kVA	Information
Overall: Pass				
Asset ID: MI054	Description: IEC LEAD	User: OLIVER	Test Instrument: X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.1	Ohm	Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
Polarity	24/06/2011			Pass
Overall: Pass				
Asset ID: MI055	Description: OVEN	User: OLIVER	Test Instrument: X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.15	Ohm	Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
Leakage	24/06/2011	0.2	mA	Pass
Load	24/06/2011	<0.05	kVA	Information
Overall: Pass				
Asset ID: MI056	Description: SCALES	User: OLIVER	Test Instrument: X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
Overall: Pass				
Asset ID: MI057	Description: ROLLER	User: OLIVER	Test Instrument: X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.07	Ohm	Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
Leakage	24/06/2011	<0.1	mA	Pass
Load	24/06/2011	0.09	kVA	Information
Overall: Pass				
Asset ID: MI058	Description: GAS MONITOR	User: OLIVER	Test Instrument: X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
Overall: Pass				

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 24/06/2011 To: 24/06/2011

Asset ID:	Description:	User:	Test Instrument:	
MI059	HEATING ELEMENT	OLIVER	X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.06	Ohm	Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
Leakage	24/06/2011	<0.1	mA	Pass
Load	24/06/2011	2.65	kVA	Information
				Overall: Pass
MI060	IEC LEAD	OLIVER	X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.05	Ohm	Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
Polarity	24/06/2011			Pass
				Overall: Pass
MI061	ADAPTER	OLIVER	X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
				Overall: Pass
MI062	SCALES	OLIVER	X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
				Overall: Pass
MI063	SIEVE SHAKER	OLIVER	X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.11	Ohm	Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
Leakage	24/06/2011	0.15	mA	Pass
Load	24/06/2011	<0.05	kVA	Information
				Overall: Pass
MI064	ADAPTER	OLIVER	X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
				Overall: Pass
MI065	SCALES	OLIVER	X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
				Overall: Pass
MI066	IEC LEAD	OLIVER	X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.09	Ohm	Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
Polarity	24/06/2011			Pass
				Overall: Pass
MI067	IEC LEAD	OLIVER	X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.09	Ohm	Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
Polarity	24/06/2011			Pass
				Overall: Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 24/06/2011 To: 24/06/2011

Asset ID: MI068	Description: OVEN	User: OLIVER	Test Instrument: X06-1324
Test Type	Date	Result	Unit Status
Visual	24/06/2011		Pass
Earth Current	24/06/2011	25	A Information
Earth	24/06/2011	0.13	Ohm Pass
Insulation	24/06/2011	>99.99	MOhm Pass
Leakage	24/06/2011	0.22	mA Pass
Load	24/06/2011	1.91	kVA Information

Overall: Pass

Asset ID: MI069	Description: OVEN	User: OLIVER	Test Instrument: X06-1324
Test Type	Date	Result	Unit Status
Visual	24/06/2011		Pass
Earth Current	24/06/2011	25	A Information
Earth	24/06/2011	0.13	Ohm Pass
Insulation	24/06/2011	17.5	MOhm Pass
Leakage	24/06/2011	0.22	mA Pass
Load	24/06/2011	1.93	kVA Information

Overall: Pass

Asset ID: MI070	Description: PENETROMETER	User: OLIVER	Test Instrument: X06-1324
-----------------	---------------------------	--------------	---------------------------

Comments: HUMBOLDT PENETROMETER HAS POWER CORD UNCLAMPED AT PLUG. LEFT IN SERVICE. RECOMMEND TO REPAIR.

Test Type	Date	Result	Unit Status
Visual	24/06/2011		Fail

Overall: Fail

Asset ID: MI071	Description: IMPACT TESTER	User: OLIVER	Test Instrument: X06-1324
-----------------	----------------------------	--------------	---------------------------

Comments: LABTHINK IMPACT TESTER HAS POWER CORD UNCLAMPED AT PLUG. LEFT IN SERVICE. RECOMMEND TO REPAIR.

Test Type	Date	Result	Unit Status
Visual	24/06/2011		Fail

Overall: Fail

Asset ID: MI072	Description: IEC LEAD	User: OLIVER	Test Instrument: X06-1324
Test Type	Date	Result	Unit Status
Visual	24/06/2011		Pass
Earth Current	24/06/2011	25	A Information
Earth	24/06/2011	0.05	Ohm Pass
Insulation	24/06/2011	>99.99	MOhm Pass
Polarity	24/06/2011		Pass

Overall: Pass

Asset ID: MI073	Description: OVEN	User: OLIVER	Test Instrument: X06-1324
Test Type	Date	Result	Unit Status
Visual	24/06/2011		Pass
Earth Current	24/06/2011	25	A Information
Earth	24/06/2011	0.08	Ohm Pass
Insulation	24/06/2011	>99.99	MOhm Pass
Leakage	24/06/2011	0.18	mA Pass
Load	24/06/2011	<0.05	kVA Information

Overall: Pass

Asset ID: MI074	Description: IEC LEAD	User: OLIVER	Test Instrument: X06-1324
-----------------	-----------------------	--------------	---------------------------

Comments: OVEN LEAD HAS NO EARTH CONNECTION. REMOVED FROM SERVICE. RECOMMEND TO REPLACE.

Test Type	Date	Result	Unit Status
Visual	24/06/2011		Pass
Earth Current	24/06/2011	25	A Information
Earth	24/06/2011	>19.99	Ohm Fail

Overall: Fail

Asset ID: MI075	Description: IEC LEAD	User: OLIVER	Test Instrument: X06-1324
-----------------	-----------------------	--------------	---------------------------

Comments: OVEN LEAD IS DAMAGED. REMOVED FROM SERVICE. RECOMMEND TO REPLACE.

Test Type	Date	Result	Unit Status
Visual	24/06/2011		Fail

Overall: Fail

Asset ID: MI076	Description: OVEN	User: OLIVER	Test Instrument: X06-1324
Test Type	Date	Result	Unit Status
Visual	24/06/2011		Pass
Earth Current	24/06/2011	25	A Information
Earth	24/06/2011	0.08	Ohm Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 24/06/2011 To: 24/06/2011

Insulation	24/06/2011	7.26	MOhm	Pass
Leakage	24/06/2011	0.23	mA	Pass
Load	24/06/2011	1.97	kVA	Information

Overall: Pass

Asset ID: MI077 Description: OVEN User: OLIVER Test Instrument: X06-1324

Comments: THERMO OVEN No.07 FAILS INSULATION TEST. POSSIBLE HEATING ELEMENT FAILURE. RECOMMEND TO REPAIR.

Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.09	Ohm	Pass
Insulation	24/06/2011	0.37	MOhm	Fail

Overall: Fail

Asset ID: MI078 Description: AIR COMPRESSOR User: OLIVER Test Instrument: X06-1324

Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.06	Ohm	Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
Leakage	24/06/2011	<0.1	mA	Pass
Load	24/06/2011	<0.05	kVA	Information

Overall: Pass

Asset ID: MI079 Description: IEC LEAD User: OLIVER Test Instrument: X06-1324

Comments: OVEN LEAD IS DAMAGED. REMOVED FROM SERVICE. RECOMMEND TO REPLACE.

Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Fail

Overall: Fail

Asset ID: MI080 Description: IEC LEAD User: OLIVER Test Instrument: X06-1324

Comments: OVEN LEAD IS DAMAGED. REMOVED FROM SERVICE. RECOMMEND TO REPLACE.

Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Fail

Overall: Fail

Asset ID: MI081 Description: IEC LEAD User: OLIVER Test Instrument: X06-1324

Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.04	Ohm	Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
Polarity	24/06/2011			Pass

Overall: Pass

Asset ID: MI082 Description: IMPACT TESTER User: OLIVER Test Instrument: X06-1324

Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	100	mA a.c.	Information
Earth	24/06/2011	0.08	Ohm	Pass
Insulation	24/06/2011	>99.99	MOhm	Pass

Overall: Pass

Asset ID: MI083 Description: OVEN User: OLIVER Test Instrument: X06-1324

Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.07	Ohm	Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
Leakage	24/06/2011	0.18	mA	Pass
Load	24/06/2011	<0.05	kVA	Information

Overall: Pass

Asset ID: MI084 Description: OVEN User: OLIVER Test Instrument: X06-1324

Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.09	Ohm	Pass
Insulation	24/06/2011	57.91	MOhm	Pass
Leakage	24/06/2011	0.22	mA	Pass
Load	24/06/2011	1.99	kVA	Information

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 24/06/2011 To: 24/06/2011

Overall: Pass

Asset ID: MI085	Description: MOTOR	User: OLIVER	Test Instrument: X06-1324	
Test Type	Date	Result	Unit	Status
Visual	24/06/2011			Pass
Earth Current	24/06/2011	25	A	Information
Earth	24/06/2011	0.06	Ohm	Pass
Insulation	24/06/2011	>99.99	MOhm	Pass
Leakage	24/06/2011	<0.1	mA	Pass
Load	24/06/2011	0.08	kVA	Information

Overall: Pass

Total Tests: 35